

## **Item 11 - Additional Tabled Paper**

### **Appendix to Closed Churchyard Report – Area Committees**

For the Western Area, a summary of the required works are as follows:

<b>Site</b>	<b>Description of works</b>	<b>Estimated cost of works</b>
St Michaels, Hartlip	Repairs to doors, paths, arch and lychgate	£26,300
St Peter & Paul, Borden	Repairs to walls, gates, paths and steps	£15,150
All Saints, Iwade	Repairs to walls, fencing and roof	£4,550